

Date: July 2019		Bench Repair Works Reference: BP001/19	
Site name/address		Chester Road, Newquay	
Local Site Information		Located along Chester Road are two benches	
Bench Reference	Grade of Disrepair	Visual Inspection	Memorial Bench (Y/N)
CR-001	3	In a state of disrepair, paint almost completely degraded. Metal frame appears degraded.	N
CR-002	3	As above.	N

Newquay Town Council

Municipal Offices, Marcus Hill, Newquay TR7 1AF
Tel: 01637 878388 Email: office@newquaycouncil.co.uk


Chester Road

SCALE: 1:1250 @ A4 DATE: 14/02/2019

MAP FILENAME: BP001/19



Map data shown may contain Ordnance Survey @ products supplied by
Pear Technology Services Ltd. Email: info@peartechnology.co.uk
© Crown Copyright and database rights from data shown above
Ordnance Survey @ licence number 100023148



Date: July 2019		Bench Repair Works Reference: BP002/19	
Site name/address		St Michaels Road, Newquay	
Local Site Information		Located along St Michaels Road is a bench by the footpath entrance	
Bench Reference	Grade of Disrepair	Visual Inspection	Memorial Bench (Y/N)
SM-001	3	In a state of disrepair, paint almost completely degraded. Metal frame appears degraded.	N



Newquay Town Council
 Municipal Offices, Marcus Hill, Newquay TR7 1AF
 Tel: 01637 878388 Email: office@newquaycouncil.co.uk

St Michaels Road

SCALE: 1:1250 @ A4 DATE: 14/02/2019

MAP FILENAME: BP002/19

Map data shown may contain Ordnance Survey products supplied by Peat Technology Services Ltd. Email: info@peattechnology.co.uk
 © Crown Copyright and database rights from data shown above
 Ordnance Survey licence number 100023148

Date: July 2019		Bench Repair Works Reference: BP003/19	
Site name/address		Pentire Road, Newquay	
Local Site Information		Pentire Road is the main road from Central Newquay to Pentire	
Bench Reference	Grade of Disrepair	Visual Inspection	Memorial Bench (Y/N)
PEN-001	PEN-001	In a state of disrepair, paint almost completely degraded. Metal frame appears degraded.	N
PEN-002	PEN-002	As above.	N
PEN-003	PEN-003	As above.	N

Newquay Town Council

Municipal Offices, Marcus Hill, Newquay TR7 1AF
Tel: 01637 878388 Email: office@newquaycouncil.co.uk


Pentire Road

SCALE: 1:1250 @ A4 DATE: 19/07/2019

MAP FILENAME: BP-003/19



Map data shown may contain Ordnance Survey products supplied by
Pear Technology Services Ltd. Email: info@peartechnology.co.uk
© Crown Copyright and database rights from data shown above
Ordnance Survey @ licence number 100023148



Date: July 2019		Bench Repair Works Reference: BP004/19	
Site name/address		Watergate Road, Newquay	
Local Site Information		Watergate Road is the main road from Newquay to Watergate Bay.	
Bench Reference	Grade of Disrepair	Visual Inspection	Memorial Bench (Y/N)
WG-001	3	In a state of disrepair, paint almost completely degraded. Metal frame appears degraded.	Y – Stewart Neil Baxendale
WG-002	0	Recently refurbished requires no maintenance	N
WG-003	3	In a state of disrepair, paint almost completely degraded. Metal frame appears degraded.	Y – Jean, Lawrence and John 'Oggie' Jordan
WG-004	3	In a state of disrepair, paint almost completely degraded. Metal frame appears degraded.	Y – Kathleen Mary Berryman

Newquay Town Council

Municipal Offices, Marcus Hill, Newquay TR7 1AF
Tel: 01637 878388 Email: office@newquaycouncil.co.uk


Watergate Road

SCALE: 1:1250 @ A4 DATE: 15/02/2019

MAP FILENAME: BP004-19



Map data shown may contain Ordnance Survey products supplied by
Pear Technology Services Ltd. Email: info@peartechnology.co.uk
© Crown Copyright and database rights from data shown above
Ordnance Survey licence number 100023148



Date: July 2019		Bench Repair Works Reference: BP005/19	
Site name/address		Leaders Road, St Columb Minor	
Local Site Information		This area is by the local Church in St Columb Minor.	
Bench Reference	Grade of Disrepair	Visual Inspection	Memorial Bench (Y/N)
LR-001	3	In a state of disrepair, paint almost completely degraded. Metal frame appears degraded.	N
LR-002	3	As above.	N

Newquay Town Council


Municipal Offices, Marcus Hill, Newquay TR7 1AF
Tel: 01637 878388 Email: office@newquaycouncil.co.uk

Leader Road

SCALE : 1 : 1250 @ A4 DATE : 15/02/2019

MAP FILENAME : BP005/19

Map data shown may contain Ordnance Survey © products supplied by
Pear Technology Services Ltd; Email: info@peartechnology.co.uk
© Crown Copyright and database rights from date shown above
Ordnance Survey © licence number 100023148



Date: July 2019		Bench Repair Works Reference: BP006/19	
Site name/address		Beachfield Gardens, Beach Road, Newquay	
Local Site Information		This open space is just off Beach Road opposite the Walkabout pub	
Bench Reference	Grade of Disrepair	Visual Inspection	Memorial Bench (Y/N)
BF-001	3	This is the last remaining Blue bench in this area. The rest have been refurbished. There are signs the wood has degraded in need of repair and restaining. The concrete frame also sees signs of wear.	Y – Edith Beryl Payne

Newquay Town Council

Municipal Offices, Marcus Hill, Newquay, TR7 1AF
Email: office@newquay.town Tel: 01637 878388


Beachfield Gardens

SCALE : 1 : 500 DATE : 03/07/2019


MAP FILENAME : BP-006-19



Map data may be © Crown copyright (and database rights) (2019) supplied under OS PSMA licence number EUL 0100050906. Terms and conditions apply. Refer to Ordnance Survey @ website.



Date: July 2019		Bench Repair Works Reference: BP007/19	
Site name/address		Doorstep Green, Treloggan Road, Newquay	
Local Site Information		This open space is just off Treloggan Road by Bookers Cash & Carry.	
Bench Reference	Grade of Disrepair	Visual Inspection	Memorial Bench (Y/N)
DS-001	2	The bench is in a state of minor disrepair, paint almost completely degraded.	N
DS-002	2	The bench is in a state of minor disrepair, paint almost completely degraded.	N
DS-003	2	The bench is in a state of minor disrepair.	N
DS-004	2	The bench is in a state of minor disrepair.	N



Date: July 2019		Bench Repair Works Reference: BP008/19	
Site name/address		Esplanade Road, Newquay	
Local Site Information		This open space is just off Esplanade Road.	
Bench Reference	Grade of Disrepair	Visual Inspection	Memorial Bench (Y/N)
ES-001	2	The bench is in a state of minor disrepair, paint almost completely degraded.	Y – Jay Holland
ES-002	2	The bench is in a state of minor disrepair, paint almost completely degraded.	Y – Roy & Joy Rainbow
ES-003	2	The bench is in a state of minor disrepair, paint almost completely degraded.	Y – Ellen Mary Carter
ES-004	2	The bench is in a state of minor disrepair, paint almost completely degraded.	Y – Alex Bender
ES-005	3	The bench here all in a state of disrepair, paint almost completely degraded.	Y – Ken Joss (Wording difficult to read)
ES-006	2	The bench is in a state of minor disrepair, paint almost completely degraded.	Y – David Williamson

Newquay Town Council

Municipal Offices, Marcus Hill, Newquay, TR7 1AF
Email: office@newquay.town Tel: 01637 878388


Esplanade Road

SCALE: 1:1250 @ A4 DATE: 17/07/2019



MAP FILENAME: BP008-19

Map data may be © Crown copyright (and database rights) (2019) supplied under OS PSMA licence number EUL 0100050806. Terms and conditions apply - Refer to Ordnance Survey website.



Location	Priority Level
Chester Road	1
St Michaels Road	3
Pentire Road	2
Esplanade Road	2
Watergate Road	3
Leader Road	3
Beachfield Gardens	1
Treloggan Doorstep Green	2